

ARBORICULTURAL SITE SUPERVISION

Tree Solutions

5, Orchard Close,
Chester, CH2 2JD

T: +44 (0)1244 389114
F: +44 (0)7075 167890
M: +44 (0)7766 774508

info@tree-solutions.co.uk
www.tree-solutions.co.uk

Planning Ref No. P/2014/0671
Developer: SG Estates
Site Address: Bryn Y Groes, Gresford
Site Agent: N/A
Visit Date: 02 September 2015
Arboricultural Supervisor: A. Henderson

Site Supervision


Was all Tree Protective Fencing in place? Yes ☒ No ☐
Was any debris noticed within Total Exclusion Zones? Yes ☐ No ☒
Are any special works scheduled for the coming building period? Yes ☐ No ☒

Details:

Are any amendments proposed to plans? Yes ☐ No ☒

Details:

Signed:



Signed: S. Griffin

(For and on behalf of Tree Solutions Ltd)

(For and on behalf of SG Estates)

Circulation:

Tree Solutions	☒
Developer Head Office	☒
Site Agent	☐
Local Planning Authority	☒
Architect	☐

ARB REF: N/A



Photos 1 – Weldmesh tree protective fencing erected in correct location around Horse Chestnut tree at site entrance



Photo 2 - Tree protective fencing with signs affixed to fence panels



Photo 3 - Scaffold pole driven into ground to prevent movement of panels



Photo 4 - Tree protective fencing around wooded area to western boundary



Photo 5 - Tree protective fencing with signs affixed along SW boundary



Photo 6 - Tree protective fencing with signs affixed around trees to NE



Photo 7 - Scaffold pole driven into ground of fencing to Pine tree to east



Photo 8 - Tree protective fencing with signs affixed erected around trees to south



Photo 9 - Tree protective fencing around Pine tree to east - note large diameter dead wood in crown that needs to be removed