







Photos of existing property depicting windows extremely rotten and damaged and damaged brickwork.


General Notes

- This document is to be used for the stated purpose only and should not be used for any other.
- Dimensions are all in millimetres, unless stated otherwise.
- It is the recipients responsibility to print this document to the correct size & scale.
- All relevant drawings and specifications should be read in conjunction with this document.
- Scaling of this document is not recommended.

North

Scale(s)

1m Scale 1:50



South-West Elevation
1 : 50




North-East Elevation
1 : 50



North-West Elevation
1 : 50



South-East Elevation
1 : 50



Project Name

Sunnyside Extension

Employer	Project Address
-	**Sunnyside, Wrexham Rd, Holt.**

RIBA Workstage	Status
2 - Concept Design	**S2 - Suitable for information**

Drawn	Created	Size
CT	**19/11/2025**	**A1**

CTA Reference	Scale	LOD	LOI
25001	**As indicated**	**1**	**1**

Document Title

Existing Elevations

Document Reference

25001 - CTA - OOSK - ZZ - DR - A - 05005

Revision Note

Issue Date	Package	Current Revision
20/03/2026		

P02