96.6m

Henblas Road

WS01 Sand at 0.4m

WS02 Clay at 0.60m

WS03 Clay at 0.60m

WS04 Sand at 1.20m

WS05 Sand at 0.45m

WS06 Sand at 0.45m

WS07 Sand at 0.60m

WS08 Sand at 0.30m

WS09 Sand at 1.60m

WS10 Sand at 1.50m

BH1 Sand at 0.60m

BH2 Clay at 0.40m

BH3 Clay at 0.3m

TH1 Sand at 1.10m

TH2 Sand at 0.50m

WREXHAM FURNITURE WAREHOUSE

WINDOWS BRICKED UP

MENS COURT 3

YARD

ACCESSWAY

CCTV survey stopped at 5.40m due to blockage, pipe was dry

CCTV Survey stopped at 32m downstream of the junction from the toilet block

Gas Spray Mark By Wales and West

Hedge ht 1.5

Hedge ht 2.0

Wall ht 0.7

Kerb

Slev 98.67
Hlev 100.16

Slev 98.69
Hlev 100.17

Slev 98.69
Hlev 100.16

Toilet Block

JH24 97.12

JH03 95.38

GS06 97.45

006A 97.13

006B 97.62

0006 97.20