You will see from the map attached to this application that tree 1 marked with a black cross has a TPO and we are not asking for permission to remove this tree.

Tree 2 marked with a red cross has a TPO and is the tree we are requesting removal of as the tree has been structurally compromised due to poor pruning creating cavities on the main trunk.